


VOLADOR

VD5/VD6 Frame instructions




1. Top plate x1
2. Middle plate x1
3. Bottom plate x1
4. Arm x4
5. CNC camera mount x2
6. Arm guard TPU x4
7. Front bumper TPU x1
8. 915 antenna TPU x2
9. Antenna TPU+GPS TPU x1
10. AI.standoff ratchet TPU x4
11. GoPro base mount x1
12. LED logo silicone x1
13. Battery anti-slip pad x1
14. XT60E-M connector x1
15. M3*23 Hex Al.standoff x4
16. M2.5*20 Hex Al.standoff x2
17. M3*28 screw x4
18. M3*16 screw x4
19. M3*12 screw x8
20. M3*10 screw x16
21. M3*10 screw w/damping ring x4
22. M3*8 screw x10
23. M2.5*9 screw x4
24. M2*12 screw x4
25. M2*5 screw x4
26. M2*18 Hex Al.standoff x1


Additional parts:

1. 20*200mm Battery strap x1
2. 20*250mm Battery strap x1
3. FlyFishRC sticker x1


1/4




2/4



3/4





4/4



Top mounting diagram

- M3*8 screw x10
- M2.5*9 screw x4
- M3*10 screw w/damping ring x4
(If not install Gopro base, change to M3*8)



Bottom mounting diagram

- M3*8 screw x10
- M3*12 screw x8
- M3*16 screw x4
- M2.5*9 screw x4
- M3*10 screw x16
- M2*12 screw x2

